There are 2 corrections noted in red in the graphic below:

Correction #1: Sew line 1 has been shortened and sew line 2 has been lengthened to go the edge of the unit.

Correction #2: Unit E4 originally labelled 2 SEC TEMP E4-1. The corrected labelling in noted below. This correction has been made on NP 999 and on TP 833.

